

JSC Safety and Health Requirements	JPR No.	1700.1
	Effective Date:	10/02/2024
	Expiration Date:	10/02/2029
	Page Number	Page 11.10-1 of 4

CHAPTER 11.10 SIGNS, WARNINGS, AND COMMUNICATING HAZARDS

11.10.1. Requirement

Communicate the hazards of working with or around asbestos materials to employees and building occupants by signs, labels, and employee information and training. Information in this chapter is based on the OSHA requirements found in 29 CFR 1926.1101.

11.10.2. Signs and labels for regulated areas and asbestos waste

11.10.2.1 Asbestos workers shall follow these requirements for signs and labels:

- a. Post signs, as required in this section and 29 CFR 1926.1101, at a distance far enough away from the Regulated Area to permit an employee to read the sign and take the necessary protective measures to avoid exposure.
- b. Additional signs may need to be posted as directed by the Competent Person after construction of workplace enclosures or during asbestos-related activities. The Competent Person should post his or her company name and telephone contact information.
- c. Barricade all Regulated Areas for Class I, II, and III work and for Class IV emergency response with ropes, tapes, or enclosures, and post signs that bear the following legend:

DANGER
ASBESTOS
CANCER AND LUNG DISEASE HAZARD
AUTHORIZED PERSONNEL ONLY
RESPIRATORS AND PROTECTIVE CLOTHING ARE
REQUIRED IN THIS AREA

The purpose of this sign is to alert employees and building occupants of the existence of the Regulated Area, thereby minimizing the number of people in the area by alerting them to the requirement that they shall have to have authorization to enter and that they take appropriate protective measures before and during entry.

- d. Label all asbestos products and containers of asbestos products with the following information:

DANGER
CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
CANCER AND LUNG DISEASE HAZARD
AVOID BREATHING ASBESTOS

JSC Safety and Health Requirements	JPR No.	1700.1
	Effective Date:	10/02/2024
	Expiration Date:	10/02/2029
	Page Number	Page 11.10-2 of 4

- e. Refer to chapter 11.13 for information on signs for waste containers. All signs and labels shall be legible, in English, and prominently displayed on the container. Commercially available signs and labels are allowed if they meet the above requirements.
- f. No label is required in instances where:
 - (1) Asbestos fibers have been modified by a bonding agent, coating or binder, or other material that prevents exposure above the action level. (Note: This exemption doesn't apply to removal operations.)
 - (2) Asbestos is present in a product concentration at less than 1%.

11.10.3. Information and training for asbestos workers

All employees who may be exposed to airborne asbestos concentrations in the course of their daily work assignments, or in excess of the PEL, shall receive training as required by Chapter 11.5 and 29 CFR 1926.1101 before, or at the time of, initial assignment.

11.10.4. Communication to employees

Each NASA or contractor organization that undertakes asbestos-related work shall inform facility occupants and employees of the nature of their work and the requirements for Regulated Areas, or any other restrictions. This requirement can be met by notifying and working with the appropriate facility manager and the work area supervisor(s), manager(s), or division chief(s) responsible for the area(s) within the affected facility. You shall never start or continue an asbestos-related activity if affected building occupants have not been notified.

11.10.5. Awareness training for building occupants

Cover general awareness training about the presence of asbestos in buildings and the “dos and don'ts” concerning Regulated Areas and suspected asbestos debris in the annual hazard communication training required of all on-site employees.

11.10.6. Labeling of mechanical rooms and conference rooms with exposed asbestos-containing materials

Asbestos workers shall post the following in mechanical and conference rooms:

- a. Post the following sign on the exterior door(s) of mechanical rooms with exposed SAI:

JSC Safety and Health Requirements	JPR No.	1700.1
	Effective Date:	10/02/2024
	Expiration Date:	10/02/2029
	Page Number	Page 11.10-3 of 4

Danger

Authorized Personnel Only
 Asbestos Insulation is Present in This Area
 Cancer and Lung Disease Hazard
 Avoid Creating Dust

Work Practices which disturb asbestos materials must be done in accordance with 29 CFR 1926.1101 and Part 11, "Asbestos Control Requirements," of JPR 1700.1. For More Information Contact the Environmental Management Office or Occupational Health Extension 36207 or 36726

- b. Place danger labels in English and Spanish near the ceiling in areas and rooms with exposed acoustical or decorative SAI. These labels shall read:

Ceiling Materials Contain Asbestos
 DO NOT DISTURB – AVOID CREATING DUST
 DANGER!
 Cancer and Lung Disease Hazard
ANY activity disturbing ASBESTOS
 must comply with OSHA

11.10.7. Labeling of buildings with asbestos-containing materials

In buildings at JSC that have ACM, post the following sign on the exterior doors.

JSC Safety and Health Requirements	JPR No.	1700.1
	Effective Date:	10/02/2024
	Expiration Date:	10/02/2029
	Page Number	Page 11.10-4 of 4

NOTICE

This Building Contains Materials Which Contain Asbestos Fibers.

Periodic air monitoring by JSC has shown that airborne fiber concentrations in this building satisfy OSHA and EPA standards.

Asbestos Fibers May be Present in the Following Building Materials;

Sprayed Applied Insulation and Acoustical Decoration

Thermal System (Pipe) Insulation

Floor Tiles and Sheet Flooring

Sheetrock/Wallboard

Roofing and Siding Materials

Ceiling Tiles

DANGER! Cutting, drilling, grinding, sanding or otherwise damaging these or any other building materials which contain asbestos can cause fiber release and asbestos exposure.

These materials can cause cancer and lung disease and should not be disturbed unless proper precautions are followed per OSHA 29 CFR 1926.1101 and Part 11, "Asbestos Control Requirements," JPR 1700.1. If any of these materials are found damaged, notify the Facility Manager, Operations Center at extensions 32038 or 33061, or Occupational Health at extension 36726. For more information call the Environmental Management Office or Occupational Health at extension 36207 or 36726.